Technical Information

Replaces technical information dated 02/11/05

Update: 08/31/2011

HAZE REMOVER

1. DESCRIPTION

HAZE REMOVER is a safe, yet very effective, viscous liquid haze remover for the removal of most ink stains and emulsion residue. To maximize its effectiveness, HAZE REMOVER is designed to be applied, dried, and then re-activated with one of our INK WASH products.

It is formulated to react during the drying process. The reaction stops once the screen is dry. This allows for reaction over several hours or even over night, without damage to the screen.

CAUTION: Do not use on nickel screens.

2. APPLICATION

APPLYING

Before using HAZE REMOVER, the screen must be reclaimed and <u>dried</u> using a water vacuum or compressed air for best results.

Apply HAZE REMOVER onto both sides of the dried screen using a sponge, rag or a stainless steel coating trough. An aluminum coating trough can be used but it will be attacked by the haze remover, so dedicate an old coating trough no longer used for coating emulsion.

NOTE: Do not pour used HAZE REMOVER back into the container as any contamination can cause the product to go bad.

DRYING

Let the treated screen dry until the HAZE REMOVER crystallizes and turns a white color on the screen. The drying time depends on mesh thickness, temperature, and humidity. Force drying with fans or in drying ovens has shown good success, but test trials are recommended. Dry screens can be left for several hours or overnight. Many customers apply HAZE REMOVER at the end of the work day and let it dry overnight.

REACTIVATING

Thorough rinsing with water, followed by a high pressure rinse is sufficient for removal of diazo stains; however, for tougher stains and ink residue, rewet the screen with INK WASH, EXCEL INK WASH, OR ULTIMATE INK WASH.

Pour or spray any of the KIWO ink wash products onto the screen and brush from both sides to re-dissolve the HAZE REMOVER. Then rinse with water and follow with a high pressure washer to remove the dissolved and emulsified residue.

NOTE: Pressure washing straight away (without rinsing first) more effectively removes ghost haze images, but should not be done without using a respirator in a well ventilated area.

KIWO INK WASH products have strong cleaning power and may attack the frame adhesive if the screen is soaked too long. Keep the soaking time as short as possible and if necessary, use a protective lacquer, such as ESTELAN B700-05 to protect the adhesive.

3. PHYSICAL DATA

Color: Clear to slightly cloudy pale yellow

Consistency: Viscous Liquid

Shelf Life: 6 months at 68° Fahrenheit

(20° Celsius)

Flash Point: Not Applicable

pH Value: ~11

TLV: 1.5 mg/m3 Sodium Hypochlorite

2 mg/m3 ceiling Sodiumhydroxide

VOC: None

Vapor Pressure: Not Applicable

HMIS rating: Health - 2 Flammability - 0

Reactivity - 1

4. PERSONAL PROTECTION

Do not breathe fumes. All working areas should be well ventilated. Avoid contact with eyes and skin. It is recommended to wear protective glasses and gloves. Use respiratory protection if exposure limits are exceeded. See Material Safety Data Sheet for additional information.

5. ENVIRONMENTAL PROTECTION

HAZE remover can be eliminated through biological decomposition in adapted waste water treatment plants. The working solution (rinsed from the screen) can generally be emptied into the drains. Consult local authorities for local regulations.

6. PACKAGING

1 US quart, 1 US gallon, 5 US gallons, 55 US gallon drums

7. ADDITIONAL INFORMATION

For additional product information, please visit our web site at www.kiwo.com. All products mentioned in this Technical Information are available through KIWO Inc. and its distributor network. For further information contact your authorized KIWO distributor or KIWO directly.

Thank you for choosing KIWO.

This data sheet is for your information, a legally binding guarantee of the product's suitability for a peculiar application cannot be derived. No responsibilities can be undertaken for occurring damages. Our products are subject to a continuous production and quality control and leave our factory in perfect condition.